

工程名稱：平溪區平溪國中校園周邊暨行車安全道路改善計畫

二、執行單位：新北市政府養護工程處

主辦單位：新北市政府養護工程處

設計監造單位：杜風工程服務顧問有限公司

施工單位：逢國營造工程有限公司


三、改善效益：

- (1) 配合交通局辦理新北市平溪國中校園周邊道路改善計畫，提供學生於一個安全、舒適之通行使用環境，並改善其周邊環境改善約250公尺。
- (2) 既有公車亭遷移及改善人行道橫波過大問題，並設置無障礙斜坡道4處
- (3) 校園周邊排水改善，並設置標線行人道，讓學生及遊客安心通行。
- (4) 遷移號誌及路燈等道路設施，使行人通行無礙。

四、改善範圍及成果：

- 1.校園周邊人行道改善508m²，排水溝改善136m。
- 2.施工時間：112/10/12~112/12/29
- 3.工程經費：785萬6,725元
- 4.改善成果：
 - (1)人行道改善長度180公尺。
 - (2)高壓磚約508平方公尺。
 - (3)無障礙坡道改善4處。
 - (5)AC路面刨鋪約2020平方公尺、孔蓋降埋3個。
 - (6)排水溝改善136公尺。
 - (7)路燈遷移3支、號誌遷移1處、新設行人號誌1處。
 - (8)其他：

五、工程位置圖示：



六、改善前後照片

照片-1(位置：平溪國中旁)

改善前	 A photograph showing a road intersection before improvement. On the left, a road with a white crosswalk leads towards a green hillside. On the right, a sidewalk runs parallel to the road, bordered by a green and white metal railing. A few people are visible in the distance.
改善後	 A photograph showing the same road intersection after improvement. The road surface is now dark asphalt. A dedicated bus lane is marked with white lines and the large white Chinese characters '公車專用' (Bus Exclusive). A yellow guardrail is installed along the left side of the road, adjacent to the green hillside. The sidewalk on the right remains the same.

照片-2(位置：平溪國中旁)

改善前



改善後



照片-3(位置：平溪國中旁)

改善前



改善後

