

A group of approximately 12 construction workers, mostly men, are gathered in a large, deep excavation site. They are wearing white hard hats and high-visibility orange safety vests over their work clothes. One man in the center, wearing a white shirt and dark trousers, is holding a microphone and gesturing with his right hand, appearing to be giving a presentation or inspection. The workers are standing on a concrete floor. The walls of the excavation are made of rough, light-colored earth or rock, with some areas covered in white plastic sheeting. Large, rusted steel beams and a crane are visible in the background, indicating a major construction project.

# 第5次聯繫會議

開會日期：115年1月5日



# 會議報告及討論議題


01.歷次會議主席裁指示事項處理情形


02.專題報告-目前施工進度與第二工區廢棄物清運執行進度

03.工地視察

04.意見交流

主席：新北市政府交通局金副局長肇安





## 與會機關或單位

臺灣新北地方檢察署、法務部調查局新北市調查處、台灣透明組織協會、新北市政府政風處  
新北市政府教育局、永平國民小學、新北市政府環保局、新北市政府警察局、新北市政府交通局  
百輝營造有限公司、大一聯合建築師事務所



# 整體進度說明(廢棄物)

